

MARYLAND VEHICLE INSPECTION REPORT

Initial Inspection **06/08/2017**
 Station Name:
HICKORY INTERNATIONAL, INC.
1704 CONOWINGO ROAD
BEL AIR, MARYLAND 21014

Result: **PASS**
 Inspector: **TODD DULEY**
 Station Number: **3978**
 Work Order Number: **37173**
 Vehicle Class: **C**

Vehicle: **2002 FREIGHTLINER CHASSIS X LINE MOT**(Initial Odometer: **27648**)
 VIN: **4UZAACHY52CK27585** Ending Odometer: **27657**
 Customer Name: **FRANKLIN HARKINS** Cert. #: **E1029837**
 Phone: **(410) 322-2601** Cert. Date: **06/19/2017**
 Address: **1120 WALTERS MILL RD FOREST HILL, MARYLAND 21050**

ROAD TEST			BRAKES			LIGHTING			SAFETY BELTS				
P	F	R	P	F	R	P	F	R	P	F	R		
Alignment Test Drive:	X		Hydraulic System:	N/A	N/A	Turn Signals:	X		Safety Belts:	X			
Service Brake Performance:	X		Drums/Discs:	X		Back Up:	X		Comments:				
Comments:			Linings/Pads:	X		Hazard:	X						
			Mechanical Linkage:	X		Brake Warning:	X						
			Booster System:	N/A	N/A	Indicator Lamps:	X		DOORS	P	F	R	
			Vacuum System:	N/A	N/A	Stop:	X		Door Handles/Latches:	X			
STEERING	P	F	R	Air System Function:	X		Tail:	X		Comments:			
Steering Wheel:	X			Air Leakage and Reserve:	X		Park:	X					
Column:	X			Air Brake Park and Emergency:	X		Side Marker:	X		GLAZING	P	F	R
Steering Coupling:	X			Actuator Reserve:	X		Reflectors:	X		Driver Door Window Mechanism:	X		
Lash:	X			Emergency Brakes:	X		Tag:	X		Windshield:	X		
Travel:	X			Parking Brake:	X		Dash:	X		Windows:	X		
Linkage:	X			Drums/Discs - Steer Axle Spec:	15.120	Clearance:		X	Tint - Left Front Window:		N/A		
Steering Box:	X			Drums/Discs - Steer Axle L Read:	N/A	ID Lamp:		X	Tint - Right Front Window:		N/A		
Power Steering:	X			Drums/Discs - Steer Axle R Read:	15.010	Headlamps:		X	Comments:				
Comments:				Drums/Discs - Axle #2 Spec:	16.620	Adjusters:	X						
				Drums/Discs - Axle #2 L Reading:	16.540	Fog/AUX Height/Aim:	X		FUEL SYSTEM	P	F	R	
				Drums/Discs - Axle #2 R Reading:	N/A	Comments: FRONT HEADLAMP LENSES GLAZED OVER. LF HAS EXCESS MOISTURE. 1 FRONT ID&CLEARANCE LTS OUT			Tank:	X			
ALIGNMENT	P	F	R	Drums/Discs - Axle #3 Spec:					Cap:	X			
Rear Wheel Alignment:	X			Drums/Discs - Axle #3 L Reading:					Tubing:	X			
Comments:				Drums/Discs - Axle #3 R Reading:		ELECTRICAL SYSTEM	P	F	R	Accelerator/Choke/Throttle:	X		
				Drums/Discs - Axle #4 Spec:		Horn:	X		Piping:	X			
SUSPENSION	P	F	R	Drums/Discs - Axle #4 L Reading:		Switches/Wiring:	X		Comments:				
Ball Joints/King Pins:	X			Drums/Discs - Axle #4 R Reading:		Auto. Trans. Neut. Safety Switches:	X						
Wheel Bearings:	X			Drums/Discs - Axle #5 Spec:		Battery:	X		BUMPERS	P	F	R	
Springs and Torsion Bars:			X	Drums/Discs - Axle #5 L Reading:		Connections:	X		Front:	X			
Air Suspension:	X			Drums/Discs - Axle #5 R Reading:		Comments:			Rear:	X			
Retractable Axle:	N/A	N/A	N/A	Drums/Discs - Axle #6 Spec:					Rear Frame:	X			
Shock Absorbers:	X			Drums/Discs - Axle #6 L Reading:		WIPERS	P	F	R	Comments:			
Ball Joints/King Pins - LU:		0		Drums/Discs - Axle #6 R Reading:		Arms/Blades:			X				
Ball Joints/King Pins - LL:		0		Drums/Discs - Axle #7 Spec:		Park Position:	X		FENDERS	P	F	R	
Ball Joints/King Pins - RU:		0		Drums/Discs - Axle #7 L Reading:		Controls:	X		Fenders:	X			
Ball Joints/King Pins - RL:		0		Drums/Discs - Axle #7 R Reading:		Comments: LF WASHER NOT CONTACTING WINDSHIELD			Comments:				
Comments: REPLACE FRONT SWAY BAR BUSHINGS/ FRAME SIDE				Drums/Discs - Axle #8 L Reading:									
				Drums/Discs - Axle #8 R Reading:		MIRRORS	P	F	R	FLOOR AND TRUNK PANS	P	F	R
EXHAUST SYSTEM	P	F	R	Linings/Pads - Steer Axle L:	N/A	Exterior:	X		Floor:	X			
Muffler:	X			Linings/Pads - Steer Axle R:	13/32	Interior:	X		Trunk:	X			
Any Piping:	X			Linings/Pads - Axle #2 L:	15/32	Comments:			Comments:				
Manifold:	X			Linings/Pads - Axle #2 R:	N/A								
Comments:				Linings/Pads - Axle #3 L:		FLAPS	P	F	R	EMISSIONS	P	F	R
				Linings/Pads - Axle #3 R:		L/R Flaps:	X		Catalytic Converter:	N/A	N/A	N/A	
WHEELS AND TIRES	P	F	R	Linings/Pads - Axle #4 L:		Comments:			Fuel Filler:	X			
Steering Axle Left:	X			Linings/Pads - Axle #4 R:					Positive Crankcase:	N/A	N/A	N/A	
Steering Axle Right:	X			Linings/Pads - Axle #5 L:		GEAR SHIFT	P	F	R	Air Injection:	X		
Axle #2 L/R In/Out:	X			Linings/Pads - Axle #5 R:		Auto. Trans. Gear Shift Indicator:			Gas Recirculation:	N/A	N/A	N/A	
Axle #3 L/R In/Out:				Linings/Pads - Axle #6 L:		Comments:			Evaporative Emissions:	N/A	N/A	N/A	
Axle #4 L/R In/Out:				Linings/Pads - Axle #6 R:					Comments:				
Axle #5 L/R In/Out:				Linings/Pads - Axle #7 L:		SPEEDOMETER/ODOMETER	P	F	R	ADDITIONAL COMMENTS			
Axle #6 L/R In/Out:				Linings/Pads - Axle #7 R:		Speedometer:	X		ALL REPAIRS COMPLETE				
Axle #7 L/R In/Out:				Linings/Pads - Axle #8 L:		Odometer:	X						
Axle #8 L/R In/Out:				Linings/Pads - Axle #8 R:		Comments:							
Comments:				Comments:									
HOOD	P	F	R										
Hood/Catches:	X												
Comments:													

RE-INSPECTION OF DEFECTS ONLY IF RETURNED WITHIN 30 DAYS AND WITHIN 1,000 MILE AND A PRORATED INSPECTION FEE MAY BE CHARGED. APPOINTMENTS FOR RE-INSPECTION MUST BE MADE AT LEAST 3 WORKING DAYS IN ADVANCE. P = PASSED F = FAILED R = REPAIRED

PLEASE NOTE: PASS RESULT IS VALID FOR 90 DAYS FOR NON-DEALER TRANSACTIONS; DEALER TRANSACTIONS THE EARLIER OF 6 MONTHS OR 1,000 MILES ADDED TO THE ODOMETER; IF RECORDED AT MVA AND RESOLD TO NEW OWNER, 30 DAYS.